





DRA POLARIS Construction updates photos – September 2025







Main building – Pour 2 2nd lift column shuttering work completed









Main building – Pour 2 2nd lift column concrete work completed









Main Building – Pour 2 Basement Backfilling and Consolidation work Completed







Main Building – Pour 2 grade slab PCC Completed







Main building – Stilt floor roof pour 2 slab shuttering work in progress







Main building – Pour 2 Stilt floor roof beam reinforcement work completed









Main building – Pour 2 Stilt floor roof beam and slab reinforcement work completed







Main building – Stilt floor roof pour 2 Electrical Work







Main building – Ramp Slab Shuttering Work







Main building – Ramp beam & slab concrete 50% completed








Main building – Pour 2 slab concrete work in progress









Main building – First Floor Pour 1 column Shuttering work









Main building – Staircase Mid landing shuttering &reinforcement work in progress







STP – Cover slab shuttering work in progress









Amenity building – Pile Integrity Test





Thank you!