



DRA POLARIS Construction update photos – January 2026


Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

STRUCTURE - PROGRESS STATUS & PHOTOS

DRA POLARIS PROGRESS TRACKING SHEET				
S.No	Activity	Block -01	Block -02	Remarks
1	Excavation	Completed	Completed	
2	Foundation	Completed	Work in progress	
3	Plinth Beam	Completed		
4	Back Filling	Completed		
5	Stilt Floor -Column	Completed		
6	Stilt Floor Roof Slab	Completed		
7	First Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work	Work in progress		
	Plastering -Internal			
8	Second Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work	Work in progress		
	Plastering -Internal			
9	Third Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work			
	Plastering -Internal			
10	Fourth Floor			
	Column	Completed		
	Roof Slab	Work in progress		
	Block Work			
	Plastering -Internal			

MASTER PLAN



Top View



North side elevation



Southwest elevation



North east elevation



East elevation



Main building – 3rd floor pour 2 roof slab Concrete work completed



Main building – 4th floor Pour 1 roof shuttering work completed



Main building – 4th floor Pour 1 roof reinforcement work completed



Main building – 4th floor Pour 1 roof slab concrete completed



Main building – 4th floor Pour 2 column concrete completed



Main building – 4th floor Pour 2 roof slab shuttering work in progress



Main building - Upper stilt floor block work in progress



Main building – 2nd floor Block work in progress



