



DRA POLARIS Construction update photos – March 2026

Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

STRUCTURE - PROGRESS STATUS & PHOTOS

DRA POLARIS				
PROGRESS TRACKING SHEET				
S.No	Activity	Block -01	Block -02	Remarks
1	Excavation	Completed	Completed	
2	Foundation	Completed	Completed	
3	Plinth Beam	Completed		
4	Back Filling	Completed		
5	Stilt Floor -Column	Completed		
6	Stilt Floor Roof Slab	Completed		
7	First Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work	Work in progress		
	Plastering -Internal			
8	Second Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work	Completed		
	Plastering -Internal	Work in progress		
9	Third Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work	Completed		
	Plastering -Internal			
10	Fourth Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work	Work in progress		
	Plastering -Internal			
11	Fifth Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work			
	Plastering -Internal			
12	Sixth Floor			
	Column	Completed		
	Roof Slab	Completed		
	Block Work			
	Plastering -Internal			
13	Seventh Floor			
	Column	Work in progress		
	Block Work			
	Plastering -Internal			

MASTER PLAN



Top view - Pour 1



Top view - Pour 2



North side elevation



South side elevation



East side elevation



West side elevation




Main building - 5th floor Pour 2 Roof Slab concrete completed



Main building – 6th floor pour 1 roof slab Concrete work completed



Main building – 6th floor pour 2 roof slab Concrete work completed



Main building – 7th floor Pour 1 column reinforcement work completed



Main building – 7th floor Pour 1 column shuttering work completed



Main building – 7th floor Pour 1 column concrete work completed



Main building – 7th floor Pour 1 slab shuttering work in progress



Main building - 2nd & 3rd floor Block work completed



Main building - 4th floor Block work 90% completed



Main building - 2nd floor wall chasing & pipe fixing work completed



Main building - 2nd floor internal plastering work in progress



*Thank
you!*