






SKYLANTIS CONSTRUCTION UPDATE PHOTOS SEPTEMBER 2024










BLOCK 1 – EIGHTH FLOOR ROOF SLAB (POUR 2) REINFORCEMENT WORKS IN PROGRESS.









BLOCK 1 – EIGHTH FLOOR ROOF SLAB (POUR 1) ELECTRICAL CONDUIT PIPE LAYING WORKS COMPLETED.







BLOCK 1 – EIGHTH FLOOR COLUMN CONCRETE WORKS COMPLETED.









BLOCK 1 – SEVENTH FLOOR ROOF SLAB CONCRETE COMPLETED.









BLOCK 1 – FIRST FLOOR INTERNAL PLASTERING WORKS COMPLETED.









BLOCK 1 – SECOND FLOOR ELECTRICAL BOX FIXING & CONCEALED PIPE COMPLETED.









BLOCK 1 – FOURTH FLOOR BLOCKWORK COMPLETED.









BLOCK 1 – FIFTH FLOOR BLOCKWORK (ABOVE LINTEL) IN PROGRESS.









BLOCK 1 – SIXTH FLOOR BLOCKWORK (SILL LEVEL) IN PROGRESS.








BLOCK 1 – NORTH SIDE ELEVATION.









BLOCK 1 – SOUTH SIDE ELEVATION.









BLOCK 2 - FOURTH FLOOR (POUR 1) COLUMN CONCRETE IN PROGRESS.








BLOCK 2 - THIRD FLOOR ROOF SLAB (POUR 1) CONCRETE COMPLETED.







BLOCK 2 FIRST FLOOR BLOCKWORK (LINTEL LEVEL) COMPLETED.








BLOCK 2 - THIRD FLOOR ROOF SLAB (POUR 1) CONCRETING WORKS COMPLETED.







BLOCK 1 TOP VIEW.









BLOCK 2 TOP VIEW









UG SUMP PCC LAYING WORKS IN PROGRESS.





Thank you!