





SKYLANTIS
CONSTRUCTION UPDATE PHOTOS FEBRUARY 2024







BLOCK 1 - STILT FLOOR ROOF SLAB WORKS COMPLETED









BLOCK 1 - FIRST FLOOR COLUMN CONCRETING WORKS COMPLETED







BLOCK 2 - FIRST FLOOR ROOF REINFORCEMENT WORKS IN PROGRESS







BLOCK 2 BACKFILLING WORKS IN PROGRESS







BLOCK 2 STILT FLOOR PCC WORK COMPLETED





Thank you!