



DRA SKYLANTIS
CONSTRUCTION UPDATE PHOTOS - SEPTEMBER 2025



EAST SIDE ELEVATION VIEW



NORTH EAST ELEVATION



NORTH WEST ELEVATION



SOUTH EAST ELEVATION



SOUTH WEST ELEVATION




WEST SIDE ELEVATION



BLOCK 1 - FIRST FLOOR CAR PARKING PLASTERING WORK IN PROGRESS



BLOCK 1 – THIRD FLOOR 1ST COAT EMULSION WORK IN PROGRESS



BLOCK 1 - CORRIDOR TILES LAYING WORK IN PROGRESS



BLOCK 1 - FIFTH FLOOR UPVC WINDOW FIXING WORK IN PROGRESS



BLOCK 1 - PLUMBING SHAFT EMULSION WORK IN PROGRESS



BLOCK 1 - STAIRCASE 2 GRANITE WORK IN PROGRESS



BLOCK 1 - TERRACE BAY 2 SCREED CONCRETE COMPLETED



BLOCK 1 - NORTH SIDE EXTERNAL TEXTURE WORK IN PROGRESS



**BLOCK 2 POUR 1 - UPTO 8TH FLOOR PRIMER (AFTER PUTTY) WORK
COMPLETED**



BLOCK 2 POUR 1 - THIRTEENTH FLOOR TILE LAYING WORK IN PROGRESS



BLOCK 2 POUR 1 - HEADROOM PLASTERING WORK IN PROGRESS



BLOCK 2 POUR 1 - TERRACE PERGOLA CONCRETE COMPLETED



**BLOCK 2 POUR 2 - THIRD & FOURTH FLOOR 1ST COAT PUTTY
WORKS IN PROGRESS**



**BLOCK 2 POUR 2 - THIRD & FOURTH FLOOR WATERPROOFING
WORKS IN PROGRESS**



BLOCK 2 POUR 2 - FOURTH TO EIGHTH FLOOR PLUMBING WORK IN PROGRESS



**BLOCK 2 POUR 2 – EIGHTH FLOOR CORNER CORRECTION IN
PROGRESS**



**BLOCK 2 POUR 2 - TENTH FLOOR INTERNAL PLASTERING
WORK IN PROGRESS**



BLOCK 2 POUR 2 - ELEVENTH FLOOR METAL BOX FIXING WORK COMPLETED



BLOCK 2 POUR 2 - TWELFTH FLOOR BLOCK WORK IN PROGRESS



BLOCK 2 POUR 2 – TERRACE FLOOR OHT CIVIL WORKS IN PROGRESS



BLOCK 2 POUR 2 – TERRACE FLOOR PERGOLA SHUTTERING WORK PROGRESS



**RAMP PARAPET WALL SHUTTERING &
REINFORCEMENT WORK IN PROGRESS**



WEST SIDE TRENCH RAFT CONCRETE WORK IN PROGRESS



COMPOUND WALL EXTERNAL PLASTERING IN PROGRESS

Thank
you!