





DRA SKYLANTIS
CONSTRUCTION UPDATE PHOTOS - JUNE 2025





Over all percentage of Completion

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to June-25	Status
1	DRA-15	Skylantis	1,85,790	62%	Structure Ongoing





STAGE COMPLETION STATUS UP TO JUNE-25

V	S. No	Description	Block 1	Block 2		% of Completion	Dam sulva
V	3. NO	Description		Pour-1	Pour-2	(Block 1&2)	Remarks
	1	Completion of Foundation	Completed	Completed	Completed	100%	
	2	Completion of Stilt Floor Roof	Completed	Completed	Completed	100%	
	3	Completion of First Floor Roof	Completed	Completed	Completed	100%	
	4	Completion of Third Floor Roof	Completed	Completed	Completed	10%	
	5	Completion of Fifth Floor Roof	Completed	Completed	Completed	100%	
	6	Completion of Seventh Floor Roof	Completed	Completed		80%	
	7	Completion of Nineth Floor Roof	Completed	Completed		80%	
	8	Completion of Eleventh Floor Roof	Completed	Completed		80%	
	09	Completion of Thirteenth Floor Roof	Completed	Completed		80%	
	10	Completion of Masonry Work	Completed	Up to 12 th Floor Completed		80%	
	11	Completion of Internal Plastering	Completed	Up to 12 th Floor Completed		70%	
1	112	Completion of Internal Finishes	Work In progress	Work In progress		25%	Tile, Painting and other finishing work in progress







NORTH WEST ELEVATION







SOUTH SIDE ELEVATION







EAST SIDE ELEVATION








BLOCK 2 POUR 2 - TOP VIEW







BLOCK 1 - SECOND FLOOR SECOND COAT PUTTY COMPLETED







BLOCK 1 – SIXTH FLOOR TILES LAYING WORK IN PROGRESS







BLOCK 1 – TENTH FLOOR SUNKEN FILLING WORK COMPLETED







BLOCK 1 – ELEVANTH FLOOR CEILING & WALL FIRST COAT PUTTY WORK IN PROGRESS







BLOCK 1 – TWELFTH FLOOR PRIMER APPLICATION WORK IN PROGRESS







BLOCK 1 - THIRTEENTH FLOOR INTERNAL PLASTERING WORK COMPLETED







BLOCK 1 – TERRACE FLOOR WATERPROOFING WORK IN PROGRESS







BLOCK 1 - EXTRENAL TEXTURE (SOUTH SIDE) WORK IN PROGRESS







BLOCK 2 POUR 1 - FIRST FLOOR TILES LAYING WORK IN PROGRESS







BLOCK 2 POUR 1 – SIXTH FLOOR WALL & CEILING PUTTY WORK IN PROGRESS







BLOCK 2 POUR 1 – TWELFTH FLOOR INNER PLASTERING COMPLETED







BLOCK 2 POUR 1 – THIRTEENTH BLOCK WORK IN PROGRESS







BLOCK 2 POUR 2 – SECOND FLOOR BLOCK WORK IN PROGRESS








BLOCK 2 POUR 2 – FIFTH FLOOR ROOF SLAB CONCRETE COMPLETED







BLOCK 2 POUR 2 – SIXTH FLOOR ROOF SLAB REINFORCEMENT WORK IN PROGRESS





Thank you!