

# DRA SKYLANTIS CONSTRUCTION UPDATE PHOTOS – MAY 2026





**VIEW FROM ENTRANCE**



**ELEVATION NORTH WEST**



**ELEVATION SOUTH EAST**



**ELEVATION EAST**



**BLOCK 1 CORRIDOR PAINTING WORKS COMPLETED**



**BLOCK 1 – STILT FLOOR LOBBY GLASSDOOR FIXING  
COMPLETED**



**BLOCK 1 TERRACE FLOOR LOBBY LIGHTING WORK IN PROGRESS**



**BLOCK 1 CORRIDOR DEEP CLEANING WORK IN PROGRESS**



**BLOCK 1 TERRACE GAZEBO WORK IN PROGRESS**



**BLOCK 1 TERRACE TILE LAYING WORK IN PROGRESS**



**BLOCK 1 TERRACE HOARDING HILTI WORK COMPLETED**



**CONNECTING CORRIDOR TILE LAYING COMPLETED**



**BLOCK 2 POUR 1 – UPTO 13<sup>TH</sup> FLOOR PAINTING COMPLETED**



**BLOCK 2 POUR 1 –LIFT 003 HANDINGOVER COMPLETED**



**BLOCK 2 POUR 1 – CORRIDOR POP REMOVING COMPLETED**



**BLOCK 2 POUR 2 – SS HANDRAIL FINISHING WORK IN PROGRESS**



**BLOCK 2 POUR 2 – TERRACE LOBBY PLASTERING WORK IN PROGRESS**



**BLOCK 2 POUR 2 – LIFT JAMBS BLOCKWORK IN PROGRESS**




**BLOCK 2 POUR 2 – CP & SANITARY FITTINGS WORK IN PROGRESS**



**BLOCK 2 POUR 2 – TERRACE TILE LAYING WORK IN PROGRESS**



**BLOCK 2 POUR 2 – 9<sup>TH</sup> FLOOR WIRING WORK IN PROGRESS**



**BLOCK 2 POUR 2 – UP TO 5<sup>TH</sup> FLOOR SWITCH PLATE FIXING COMPLETED**



**BLOCK 2 POUR 2 – 2<sup>ND</sup> COAT PAINTING WORK IN PROGRESS**



**GYM & MPH STRUCTURAL GLAZING INSTALLATION WORK IN PROGRESS**



**MULTIPURPOSE HALL FLUTED PANEL FIXING WORK IN PROGRESS**



**ENTRANCE GSB LEVELLING WORK IN PROGRESS**



**STREET LIGHT FIXING WORK IN PROGRESS**



**KIDS PLAY AREA SAND SEA FILLING IN PROGRESS**



**BLOCK 1 STILT FLOOR COLUMN GUARD FIXING WORK IN PROGRESS**



**SOUTH EAST CORNER LANDSCAPING RED SOIL FILLING WORK IN PROGRESS**

Thank  
you!