

DRA SKYLANTIS

MONTHLY CONSTRUCTION PHOTOS –JUNE 2026





VIEW FROM ENTRANCE



ELEVATION NORTH WEST



ELEVATION SOUTH EAST



ELEVATION EAST



**BLOCK TERRACE HOARDING BEAM REINFORCEMENT IN
PROGRESS**



BLOCK 1 – TERRACE FLOOR GRID GRANITE WORK IN PROGRESS



BLOCK 1 FIRST FLOOR LOBBY PAINTING WORK IN PROGRESS



BLOCK 1 TERRACE LOBBY GLASSDOOR FIXING COMPLETED



BLOCK 1 TERRACE GAZEBO WORK IN PROGRESS



BLOCK 2 POUR 1 TERRACE PERGOLA WORK COMPLETED



BLOCK 2 TERRACE LANDSCAPE TILE LAYING WORK IN PROGRESS




LIFT 004 CABIN ERECTION COMPLETED



BLOCK 2 CORRIDOR PAINTING WORK IN PROGRESS



BLOCK 2 CONNECTING CORRDIOR WINDOW FIXING COMPLETED



BLOCK 2 POUR 1 – STILT FLOOR LOBBY FINISHING WORK IN PROGRESS



BLOCK 2 POUR 2 – STILT LOBBY FINISHING WORK IN PROGRESS



STILT & 1ST FLOOR CAR PARKING MARKING COMPLETED



SPEED BREAKER FIXING COMPLETED



ENTRANCE AREA PAVER BLOCK LAYING WORK IN PROGRESS



EXTERNAL CAR PARKING MARKING COMPLETED



GYM & MPH FINISHING WORK IN PROGRESS



WTP PUMP ROOM PAINTING WORK COMPLETED



LETTER BOX FIXING COMPLETED



WALKWAY PAVER LAYING WORK IN PROGRESS



ENTRANCE GATE FIXING COMPLETED

*Thank
you!*