



DRA SKYLANTIS
CONSTRUCTION UPDATE PHOTOS - JULY 2025



VIEW FROM ENTRANCE



NORTH EAST ELEVATION



NORTH WEST ELEVATION



SOUTH EAST ELEVATION



SOUTH SIDE ELEVATION



EAST SIDE ELEVATION



BLOCK 1 - TOP VIEW



BLOCK 2 POUR 1 - TOP VIEW



BLOCK 2 POUR 2 - TOP VIEW



**BLOCK 1 – FIFTH FLOOR STAIRACSE GRANITE LAYING
WORK IN PROGRESS**



**BLOCK 1 – SIXTH & SEVENTH FLOOR SECOND COAT PUTTY
WORK IN PROGRESS**



BLOCK 1 – EIGHTH FLOOR TILES LAYING WORK IN PROGRESS



**BLOCK 1 – NINTH FLOOR TOILET WALL TILES LAYING
WORK IN PROGRESS**



**BLOCK 1 – TWELFTH FLOOR PLUMBING SUSPENDED LINE
WORK COMPLETED**



**BLOCK 1 – THIRTEENTH FLOOR PLUMBING
CONCEALED LINE COMPLETED**



**BLOCK 1 – TERRACE BAY 1 SCREED CONCRETE BUTTON MARK
FIXING WORK IN PROGRESS**



**BLOCK 1 – NORTH SIDE EXTERNAL PLASTERING
WORK IN PROGRESS**



**BLOCK 1 – SOUTH SIDE EXTRENAL PLASTERING
WORK IN PROGRESS**



**BLOCK 1 – EAST SIDE EXTERNAL PLASTERING
WORK IN PROGRESS**



**BLOCK 1 – SOUTH SIDE EXTRENAL TEXTURE
WORK IN PROGRESS**



**BLOCK 2 POUR 1 – FOURTH & FIFTH TILES LAYING
WORK IN PROGRESS**



**BLOCK 2 POUR 1 – SEVENTH & EIGHTH CEILING PUTTY
WORK IN PROGRESS**



**BLOCK 2 POUR 1 – EIGHTH & NINTH FLOOR PLUMBING SUSPENDED
LINE WORK IN PROGRESS**



**BLOCK 2 POUR 1 – NINTH FLOOR TOILET ELECTRICAL
WORK IN PROGRESS**



**BLOCK 2 POUR 1 – TWELFTH SUNKEN WATER PROOFING
WORK IN PROGRESS**



**BLOCK 2 POUR 1 – THIRTEENTH FLOOR INNER PLASTERING
COMPLETED**



**BLOCK 2 POUR 2 – FIRST FLOOR GYM INTERNAL PLASTERING
WORK IN PROGRESS**



BLOCK 2 POUR 2 – SECOND FLOOR BLOCK WORK COMPLETED



BLOCK 2 POUR 2 – THIRD FLOOR BLOCK WORK IN PROGRESS



BLOCK 2 POUR 2 – FOURTH FLOOR BLOCK WORK IN PROGRESS



BLOCK 2 POUR 2 – FIFTH FLOOR BLOCK WORK IN PROGRESS



**BLOCK 2 POUR 2 – NINTH FLOOR ROOF SLAB
CONCRETE COMPLETED**



**BLOCK 2 POUR 2 – TENTH FLOOR COLUMN
CONCRETE IN PROGRESS**



BLOCK 2 SOUTH SIDE EXTERNAL PLASTERING WORK IN PROGRESS



BLOCK 2 WEST SIDE EXTERNAL PLASTERING WORK IN PROGRESS



STP COVER SLAB CONCRETE COMPLETED



STP EXTERNAL WATERPROOFING COATING WORK IN PROGRESS



STP EXTERNAL BACK FILLING WORK IN PROGRESS



COMPOUND WALL EAST SIDE – BLOCK WORK IN PROGRESS



COMPOUND WALL WEST SIDE - RR MASONRY WORK COMPLETED

Thank
you!