



DRA SKYLANDTIS
CONSTRUCTION UPDATE PHOTOS - DECEMBER 2025



ELEVATION FROM ENTRANCE



ELEVATION NORTH EAST



ELEVATION NORTH WEST



EL E V A T I O N S O U T H E A S T



ELEVATION EAST



ELEVATION SOUTH



ELEVATION WEST



**BLOCK 1 STILT FLOOR SUSPENDED LINE & RING MAIN LINE
WORKS IN PROGRESS**




**BLOCK 1 STILT FLOOR FIRE FIGHTING HYDRANT
PIPE LAYING WORK IN PROGRESS**



BLOCK 1 FIRST FLOOR CAR PARK AREA PLUMBING WORK IN PROGRESS



**BLOCK 1 FIRST FLOOR CAR PARK AREA FIRE FIGHTING WORK IN
PROGRESS**



BLOCK 1 STAIRCASE SS HANDRAIL WORKS IN PROGRESS



BLOCK 1 OTS WATERPROOFING WORKS IN PROGRESS



BLOCK 1 UP TO 6TH FLOOR WIRING WORKS IN PROGRESS



BLOCK 1 UPTO 6TH FLOOR DOOR FIXING WORKS COMPLETED



**BLOCK 1 UPTO 10TH FLOOR WINDOW GRILLS FIXING WORKS
COMPLETED**



**BLOCK 1 UPTO 13TH FLOOR UPVC WINDOW FIXING WORKS
COMPLETED**



BLOCK 1 TERRACE SCREED COMPLETED



BLOCK 1 – TERRACE OHT LADDER FIXING WORK COMPLETED



BLOCK 1- EAST SIDE EXTERNAL EMULSION 1ST COAT COMPLETED



**BLOCK 1- SOUTH SIDE EXTERNAL EMULSION 1ST COAT WORK IN
PROGRESS**



**BLOCK 1- NORTH SIDE EXTERNAL EMULSION 1ST COAT WORK IN
PROGRESS**



**BLOCK 1- PASSENGER LIFTS DOOR FRAME FIXING WORK IN
PROGRESS**



**BLOCK 2 POUR 1 – INTERNAL FLATS 1ST COAT EMULSION
COMPLETED**



**BLOCK 2 POUR 1 – DINING WASH BASIN GRANITE COUNTERTOP
WORK IN PROGRESS**



BLOCK 2 POUR 1- 2 SERIES SUNKEN FILLING WORK COMPLETED



**BLOCK 2 POUR 1 – TERRACE PU WATERPROOFING WORK
COMPLETED**



BLOCK 2 POUR 2 – 6TH FLOOR TILES LAYING WORK IN PROGRESS



**BLOCK 2 POUR 2 – 12TH & 13TH FLOOR CORRIDOR CEILING CORNER
CORRECTION WORK IN PROGRESS**



**BLOCK 2 POUR 2 –SUNKEN WATERPROOFING WORK
COMPLETED**



BLOCK 2 POUR 2 –SUNKEN FILLING WORK COMPLETED



**BLOCK 2 POUR 2 – 12TH & 13TH FLOOR CORRIDOR WALL
PRIMER WORK IN PROGRESS**



**BLOCK 2 POUR 2 – TOILET SUSPENDED PLUMBING LINE
COMPLETED**



RAMP COVER SLAB CONCRETE COMPLETED



**BLOCK 2 POUR 2 – WEST SIDE EXTERNAL TEXTURE WORK
COMPLETED**



**BLOCK 2 POUR 2 – SOUTH SIDE EXTERNAL TEXTURE WORK IN
PROGRESS**



CONNECTING BRIDGE SLAB CONCRETE WORK COMPLETED



STP – PUMP ROOM PRIMER WORK COMPLETED



ENTRANCE ARCH FOUNDATION WORK IN PROGRESS



TRENCH RCC WALL CONCRETE WORK IN PROGRESS



COMPOUND WALL INTERNAL PLASTERING WORK IN PROGRESS



COMPOUND WALL EXTERNAL PLASTERING WORK IN PROGRESS

Thank
you!