



DRA SKYLANDTIS
CONSTRUCTION UPDATE PHOTOS - JANUARY 2026



VIEW FROM ENTRANCE



ELEVATION NORTH EAST



EL E V A T I O N N O R T H W E S T



ELEVATION SOUTH EAST



ELEVATION EAST



ELEVATION SOUTH



ELEVATION WEST



**BLOCK 1 STILT FLOOR SUSPENDED LINE & RING MAIN LINE
COMPLETED**



**FIRE FIGHTING HYDRANT
PIPE LAYING WORK IN PROGRESS**



BLOCK 1 STAIRCASE SS HANDRAIL WORKS IN PROGRESS



BLOCK 1 PASSENGER LIFT INSTALLATION WORK IN PROGRESS



BLOCK 1 UP TO 13TH FLOOR WIRING WORKS IN PROGRESS




BLOCK 1 UPTO 10TH FLOOR MAIN DOOR FIXING WORKS IN PROGRESS



**BLOCK 1 UPTO 3RD FLOOR CP & SANITARY FITTINGS FIXING
WORK IN PROGRESS**



BLOCK 1- EXTERNAL EMULSION 1ST COAT COMPLETED



BLOCK 2 POUR 1 – LIFT WATERPROOFING WORK IN PROGRESS



BLOCK 2 POUR 1 – BALCONY GLASS HANDRAIL FIXING WORK IN PROGRESS



BLOCK 2 POUR 1- UPVC WINDOWS FIXING WORK IN PROGRESS



**BLOCK 2 POUR 2 – UPTO 8TH FLOOR TILES LAYING WORK
COMPLETED**



**BLOCK 2 POUR 2 – 9TH FLOOR TILE LAYING WORK IN
PROGRESS**



**BLOCK 2 POUR 2 –UPTO 13TH FLOOR 1ST COAT PUTTY
COMPLETED**



**BLOCK 2 POUR 2 – UPTO 13TH FLOOR TOILET SUSPENDED
PLUMBING LINE COMPLETED**



**BLOCK 2 POUR 2 STAIRCASE GRANITE LAYING WORK IN
PROGRESS**




**BLOCK 2 POUR 2 – WEST SIDE EXTERNAL PRIMER WORK
COMPLETED**



**BLOCK 2 POUR 2 – SOUTH SIDE EXTERNAL PRIMER WORK IN
PROGRESS**



**STP – PUMP ROOM ELECTROMECHANICAL WORK
IN PROGRESS**



STP – PUMP ERECTION WORK IN PROGRESS



SEWAGE CHAMBER WORK IN PROGRESS



STROM WATER DRAIN - TRENCH WORK IN PROGRESS



ELECTRICAL HUME PIPE LAYING WORK IN PROGRESS



COMPOUND WALL PRIMER WORK IN PROGRESS

Thank
you!