



DRA SKYLANTIS
CONSTRUCTION UPDATE PHOTOS - MARCH 2026



VIEW FROM ENTRANCE



ELEVATION NORTH EAST



ELEVATION NORTH WEST



ELEVATION SOUTH EAST



ELEVATION EAST



BLOCK 1 STILT FLOOR SCREED COMPLETED




**CARK PARK PLUMBING PIPE SHERA BOARD COVERING WORK IN
PROGRESS**




BLOCK 1 STILT FLOOR LOBBY GRANITE FLOORING WORK IN PROGRESS



BLOCK 1 PASSENGER LIFT-1 INSTALLATION WORK COMPLETED



**BLOCK 1 PASSENGER LIFT-2 CABIN INSTALLATION WORK IN
PROGRESS**



BLOCK 1 CCTV CAMERA INSTALLATION WORK IN PROGRESS



**BLOCK 1 ELEVENTH FLOOR ELECTRICAL TESTING WORK IN
PROGRESS**



**BLOCK 1 NINTH FLOOR FINAL COAT EMULSION WORK IN
PROGRESS**




BLOCK 1 5TH FLOOR DEEP CLEANING WORKS IN PROGRESS



BLOCK 1 UP TO 13TH FLOOR CP & SANITARY FITTINGS FIXING WORKS COMPLETED



BLOCK 1 UPTO 13TH FLOOR DOOR FIXING WORKS COMPLETED



BLOCK 1 UPTO 13TH FLOOR SOAP WASH WORKS COMPLETED



**BLOCK 1 EXTERNAL ALUMINIUM LOUVER FIXING WORK
COMPLETED**



**BLOCK 1 COMMON AREA UPVC WINDOWS FIXING WORK IN
PROGRESS**



BLOCK 1 EXTERNAL FINAL COAT EMULSION WORK IN PROGRESS



BLOCK 2 POUR 1 – UPTO 13TH FLOOR GRILL FIXING WORK IN PROGRESS



BLOCK 2 POUR 1 – UPTO 6TH FLOOR POP REMOVING WORK IN PROGRESS



BLOCK 2 POUR 1 – UPTO 6TH FLOOR DOOR FIXING WORKS IN PROGRESS



BLOCK 2 POUR 1 – UPTO 4TH FLOOR INTERNAL WIRING WORK IN PROGRESS



BLOCK 2 POUR 1 – EXTERNAL LOUVER FIXING WORK IN PROGRESS



BLOCK 2 POUR 1 – CORRIDOR UPVC WINDOWS FIXING WORK IN PROGRESS



BLOCK 2 POUR 1 – GRID FALSE CEILING FIXING WORK COMPLETED



BLOCK 2 POUR 1 – PVT TERRACE GEOXTILE LAYING WORK IN PROGRESS



BLOCK 2 POUR 1 – STAIRCASE SS HANDRAIL FIXING WORK IN PROGRESS



BLOCK 2 – CORRIDOR TILE LAYING COMPLETED



**BLOCK 2 POUR 2 – TERRACE PU WATERPROOFING & SCREED CONCRETE
COMPLETED**



**BLOCK 2 POUR 2 – GYM & MULTI PURPOSE HALL WATERLINE & FLUSH TANK
FIXING WORK IN PROGRESS**



BLOCK 2 POUR 2 –UPVC WINDOW & DOORS FIXING WORK IN PROGRESS



BLOCK 2 POUR 2 – 4TH FLOOR DOOR FIXING WORK IN PROGRESS



BLOCK 2 POUR 2 – BALCONY GLASS RAIL BOTTOM PROFILE FIXING IN PROGRESS



BLOCK 2 POUR 2 – CORRIDOR WINDOW FIXING WORK IN PROGRESS



BLOCK 2 POUR 2 – 8TH FLOOR 1ST COAT EMULSION WORK IN PROGRESS



RAMP EXTERNAL TEXTURE PUTTY WORK IN PROGRESS



SECURITY CABIN BLOCKWORK IN PROGRESS



BLOCK 1 & 2 EB PANEL INSTALATION WORK IN PROGRESS



HNS PUMP INSTALATION COMPLETED



WTP & FIRE PUMP INSTALATION COMPLETED



STP PUMP INSTALATION COMPLETED



BLOCK 2 PARTIAL CAR PARKING SCREED CONCRETE COMPLETED



EAST SIDE PAVER BLOCK LAYING WORK IN PROGRESS



TRANSFORMER YARD CIVIL WORKS IN PROGRESS



COMPOUND WALL 1ST COAT EMULSION WORK IN PROGRESS



UG SUMP TOP SLAB WATERPROOFING WORKS COMPLETED



ENTRANCE AREA COMPOUND WALL RR MASONRY WORK IN PROGRESS

Thank
you!