

DRA TRINITY – CONSTRUCTION UPDATE PHOTOS – MAY 2026



STAGE COMPLETION STATUS UP TO MAY 2026'			
S. No	Description	Status	Remarks
1	Completion of Pile Foundation	Completed	
2	Commencement of Stilt Floor Roof Level	Completed	
3	Commencement of 1st Floor Roof Level	Completed.	
4	Commencement of 2nd Floor Roof Level	Completed.	
5	Commencement of 3rd Floor Roof Level	Completed.	
6	Commencement of 4th Floor Roof Level	Completed.	
7	Commencement of 5th Floor Roof Level	Completed.	



Front View



North Side View.



South Side View.



West Side View.



Main Building Terrace Press Tiles Work Nearing Completion.



**Main Building Terrace Solar Pannel Fixing
Work Nearing Completion.**



Multipurpose Hall AC Fixing Work Completed.



GYM AC Fixing Work Completed.



Kids Play Equipment's Fixing Work In Progress.



Main Building Pour-1 UP To 5th Floor Flat Door Fixing Work Completed.



Main Building Pour-2 Up to 2nd Floor Flat Door Fixing Work Completed.



**Main Building Pour-1 Up To 5th Floor 1st Coat Painting
Work Completed.**



Main Building Pour-2 Up To 3rd Floor 1st Coat Painting Work Completed.



Main Building Pour-2 4th Floor Putty Work Completed.



Main Building Pour-2 Electrical Up to 4th Floor Flat Wiring Work In Progress.



Main Building Pour-1 Electrical Up to 5th Floor Flat Wiring Work In Progress.



**Main Building 1st Floor Electrical Switch Plate Fixing
Work In Progress.**



**Main Building Pour-1 Up to 5th Floor Cp and Sanitary Fixing
Work In Progress.**



Main Building Pour-1 Up to 5th Floor Toilet Grid False Ceiling Channel Fixing Work Completed.



Main Building Pour-1 Stilt Floor Plumbing Work Nearing Completion.



Main Building Pour-2 Stilt Floor Plumbing Work Nearing Completion.



Main Building Pour-1 & 2 Lift Fixing Work In Progress.



**Main Building Pour-1 Lift Granite Wall Glazing
Work Nearing Completion.**



Main Building Pour-2 5th floor Tiles Work Completed.



Main Building Pour-1 Up To 5th floor Tiles Acid Wash Work Completed.



Main Building Pour-2 1st floor Tiles Acid Wash Work In Progress.



Main Building Up to 5th Floor Corridor Tiles Laying Work Completed.



Main Building Pour-1 Stilt Floor Grano Flooring Work Completed.



**Main Building Stilt Floor Granite Lobby Flooring
Work Nearing Completion.**



**Main Building Plumbing Shaft Shera Plank Covering
Work Nearing Completion.**



**Main Building Balcony Plumbing Shaft Shera Door Fixing
Work In Progress.**



Main Building Balcony Handrail Fixing Work Nearing Completion.



Main Building Pour-1 Window Grill Fixing Work Completed.



**Main Building AC Outdoor Handrail Fixing
Work Nearing Completion.**



**Main Building South Side External Texture Painting
1st Coat Work In Progress.**



**Main Building West Side External Texture Painting
1st Coat Work Completed.**



**Main Building North Side External Texture Painting
1st Coat Work Completed.**



**Main Building Pour-2 North Side External Texture Painting
1st Coat Work Completed.**



UG Sump Pump and Filter Fixing Work In Progress.



STP Pump and Filter Fixing Work In Progress.



**STP Pump Room Walkway Platform Channel Fixing
Work In Progress.**



DG Exhaust Pipe Fixing Work Completed.



Compound Wall External Plastering Work Nearing Completion.



Storm Water Drain Top Finishing Work Nearing Completion.

*Thank
you!*