

# DRA TRINITY – MONTHLY CONSTRUCTION PHOTOS JUNE 2026



STAGE COMPLETION STATUS UP TO JUNE 2026'			
S. No	Description	Status	Remarks
1	Completion of Pile Foundation	Completed	
2	Commencement of Stilt Floor Roof Level	Completed	
3	Commencement of 1st Floor Roof Level	Completed.	
4	Commencement of 2nd Floor Roof Level	Completed.	
5	Commencement of 3rd Floor Roof Level	Completed.	
6	Commencement of 4th Floor Roof Level	Completed.	
7	Commencement of 5th Floor Roof Level	Completed.	



**Front View**



**North Side View.**



**South Side View.**



**Main Building Terrace Press Tiles Work Completed.**



**Main Building Terrace Solar Pannel Fixing  
Work Completed.**



**Multipurpose Hall AC Fixing and Electrical Wiring Work Completed.**



**Multipurpose Hall False Ceiling Work Nearing Completion.**



**Multipurpose Hall Elevation Glass Fixing Work Completed.**



**GYM AC Fixing and Electrical Wiring Work Completed.**



**GYM AC False Ceiling Work Nearing Completion.**



**Kids Play Area Flooring Work Completed.**



**Main Building Pour-2 UP To 5<sup>th</sup> Floor Flat Door  
Fixing Work Completed.**



**Main Building Pour-2 UP To 5<sup>th</sup> Floor Window Fixing  
Fixing Work Completed.**



**Main Building UP To 5<sup>th</sup> Floor Balcony Sliding Door Fixing  
Fixing Work Completed.**



**Main Building Pour-2 Up To 5<sup>th</sup> Floor 1<sup>st</sup> Coat Painting  
Work Completed.**



**Main Building 1<sup>st</sup> and 2<sup>nd</sup> Floor Corridor Putty Work Completed.**



**Main Building Pour-1 Electrical Up to 5<sup>th</sup> Floor Flat Wiring and Switch Plate Fixing Work Completed.**



**Main Building Pour-2 Electrical Up to 4<sup>th</sup> Floor Flat Wiring and Switch Plate Fixing Work Completed.**



**Main Building Electrical Up to 3<sup>rd</sup> Floor Flat Electrical Power Testing Work Completed.**



**Main Building Pour-1 Up to 5<sup>th</sup> Floor Cp and Sanitary Fixing Work Nearing Completion.**



**Main Building Pour-2 Up to 3<sup>th</sup> Floor Sanitary Fixing  
Work In Progress.**



**Main Building Up to 5<sup>th</sup> Floor Toilet Grid False Ceiling  
Channel and Board Fixing Work Completed.**



**Main Building Pour-1 Stilt Floor Plumbing Work Completed.**




**Main Building Pour-2 Stilt Floor Plumbing Work Nearing Completion.**



**Main Building Pour-1 Lift Fixing Work Completed.**



**Main Building Pour-2 Lift Fixing Work Nearing Completion.**



**Main Building Lift Granite Wall Cladding Work Completed.**



**Main Building Pour-2 Up To 5<sup>th</sup> floor Tiles Acid Wash Work Completed.**



**Main Building Up to 5<sup>th</sup> Floor Corridor Light Fixing Work Completed.**



**Kids Play Area Light Fixing Work Completed.**



**Main Building Pour-2 Stilt Floor Grano Flooring Work Completed.**



**Electrical and Communication Shaft Door Fixing  
Work In Progress.**



**Main Building Plumbing Shaft Shera Plank Covering  
Work Completed.**



**Main Building Balcony Plumbing Shaft Shera Door Fixing Work Completed.**



**Main Building Balcony Plumbing Shaft Aluminum Louvers Fixing  
Work In Progress.**



**Main Building Balcony Handrail Fixing Work Completed.**



**Main Building Pour-1 Window Grill Fixing Work Completed.**



**Main Building AC Outdoor Handrail Fixing Work Completed.**



**Main Building South Side External Texture Painting  
1<sup>st</sup> Coat Work Completed.**



**UG Sump Pump and Filter Fixing Work Completed.**



**UG Sump Pump Room Staircase Tiles Laying Work Completed.**



**STP Pump and Filter Fixing Work Completed.**



**STP Pump Room Staircase Tiles Laying Work Completed.**



**STP Pump Room Walkway Platform Channel Fixing  
Work Completed.**



**DG Commissioning Work Completed.**



**Transformer, RMU and Pannel Box Fixing Work Completed.**



**Compound Wall Internal Texture and Primer Work Completed.**



**Storm Water Drain Cover Slab Fixing Work Completed.**



**External Driveway Paver Block Laying Work In Progress.**

*Thank  
you!*