



DRA TRINITY – CONSTRUCTION UPDATES AUGUST 2025

STAGE COMPLETION STATUS UP TO AUGUST 2025'

S. No	Description	Status	Remarks
1	Completion of Pile Foundation	Completed	
2	Commencement of Stilt Floor Roof Level	Completed	
3	Commencement of 1st Floor Roof Level	Completed.	
4	Commencement of 2nd Floor Roof Level	Completed.	
5	Commencement of 3rd Floor Roof Level	Completed.	
6	Commencement of 4th Floor Roof Level	Pour-1 work Completed.	Pour-2 Roof Slab Shuttering Work In Progress
7	Commencement of 5th Floor Roof Level	Pour-1 work Completed.	



East Side View



North Side View.



South Side View.



Main Building Pour-1 Staircase Head Room Shuttering Work Completed.



Main Building Pour-1 Terrace Floor Parapet Wall Blockwork Work Completed.



Main Building 5th Floor Pour-1 Blockwork Work In Progress.



Main Building 4th Floor Pour-1 Blockwork Work Completed.



Main Building Pour-1 1st Floor Electrical Box Fixing and Pipe Laying Work Completed.



Main Building Pour-1 2nd Floor Electrical Box Fixing and Pipe Laying Work Completed.



**Main Building Pour-1 3rd Floor Electrical Box Fixing and Pipe Laying
Work In Progress.**



**Main Building Pour-1 1st Floor Plumbing Toilet Concealed pipe Line
Work In Progress.**



Main Building Pour-1 1st Floor Flat Plastering Work Nearing Completion.



**Main Building Pour-2 2nd Floor Roof Slab Shuttering
Work Completed.**



Main Building Pour-2 2nd Floor Roof Slab Reinforcement Work Completed.



Main Building Pour-2 2nd Floor Roof Slab Concrete Work Completed.



Main Building Pour-2 3rd Floor Column Concrete Work Completed.



**Main Building Pour-2 3rd Floor Roof Slab Shuttering
Work Completed.**



**Main Building Pour-2 3rd Floor Roof Slab Reinforcement
Work Completed.**



Main Building Pour-2 3rd Floor Roof Slab Concrete Work Completed.



**Main Building Pour-2 4th Floor Column Concrete South Side
Work Completed.**



**Main Building Pour-2 4th Floor Roof Slab Shuttering
Work Commenced.**



**Main Building Pour-2 1st Floor Blockwork
Work In Progress.**



**Main Building Stilt Floor Blockwork Up to Lintel Level
Work Completed.**



**Main Building Stilt Floor Manhole Blockwork and plastering
Work Nearing completion.**



**Main Building External Storm Water Drain PCC
Work Nearing completion.**

*Thank
you!*