





DRA TRINITY – CONSTRUCTION UPDATES SEPTEMBER 2025







Front View







North Side View.








South Side View.









Main Building 5th Floor Pour-1 Blockwork Completed.







Main Building 5th Floor Pour-1 Plastering Work In Progress.









Main Building 4th Floor Pour-1 plastering Work Completed.








Main Building Pour-1 5th Floor Electrical Box Fixing and Pipe Laying Work Completed.








Main Building Pour-2 4th Floor Roof Slab Shuttering and Reinforcement Work Completed.








Main Building Pour-2 4th Floor Roof Slab Concrete Work Completed.







Main Building Pour-2 5th Floor Column Concrete Work Completed.









Main Building Pour-2 5th Floor Roof Slab Shuttering and Reinforcement
Work Nearing Completion.







Main Building Pour-2 Terrace Floor Slab South Side Concrete Work Completed.







Main Building Pour-2 1st Floor Blockwork Work Completed.







Main Building Pour-2 2nd Floor Blockwork Work Nearing Completion.







Main Building Pour-2 3rd Floor Blockwork Up to Sill Level Work Completed.








Main Building Pour-2 4th Floor Blockwork Work In Progress.









Main Building External Strom Water Drain RCC wall Concrete Work Nearing completion.





Thank you!