





North Side View.



South Side View.



Main Building Terrace Blockwork Work Completed.



Main Building Pour-1 Terrace Plastering Work Completed.



Main Building Pour-2 Terrace Plastering Work In Progress.



Main Building Pour-1 Terrace Waterproofing Preparation Work In Progress.



Main Building Terrace Over Head Tank Waterproofing Work Completed.



Main Building Pour-2 5th Floor Blockwork Work Completed.



Main Building Pour-2 5th Floor Plastering Work In Progress.



Main Building Pour-2 4th Floor Plastering Work Completed.



Main Building Pour-1 and Pour-2 Lift Plastering Work Completed.



Main Building Pour-2 Podium Area Blockwork Work Nearing Completion.



**Main Building Pour-2 5th Floor Electrical Box Fixing and Pipe Laying
Work Completed.**



Main Building Pour-1 Up to 5th Floor Plumbing Work Completed.



Main Building Pour-1 Up to 5th Floor Plumbing Work Completed.



Main Building Pour-1 Plumbing Shaft Pipe Laying Work In Progress.



**Main Building Pour-2 Up to 3rd Floor Plumbing Toilet Wall Chasing
Work Completed.**



Main Building Pour-2 1st Floor Sunken Waterproofing Work Completed.



**Main Building Pour-2 2nd Floor Sunken Waterproofing
Work Completed.**



**Main Building Pour-1 Up to 5th Floor Wall Putty 1 Coat
Work Completed.**



**Main Building Pour-1 Up to 5 Floor Corridor 1 coat Putty
Work In Progress .**



Main Building Pour-1 1st floor Tiles Work Commenced.



Main Building External 9th and 10th Series Work Plastering Completed.



**Main Building South Side External 8th&7th Series Plastering
Work Completed.**



**Main Building South Side External 6th & 5th Series Plastering
Work Completed.**



Compound Wall Entrance Blockwork Work Nearing Completion.

Thank
you!