



DRA TRINITY – CONSTRUCTION UPDATES JANUARY 2026

STAGE COMPLETION STATUS UP TO JANUARY 2026'

S. No	Description	Status	Remarks
1	Completion of Pile Foundation	Completed	
2	Commencement of Stilt Floor Roof Level	Completed	
3	Commencement of 1st Floor Roof Level	Completed.	
4	Commencement of 2nd Floor Roof Level	Completed.	
5	Commencement of 3rd Floor Roof Level	Completed.	
6	Commencement of 4th Floor Roof Level	Completed.	
7	Commencement of 5th Floor Roof Level	Completed.	



Front View



North Side View.



South Side View.



Main Building Pour-2 Terrace Plastering Work In Progress.



Main Building Pour-1 Terrace Waterproofing nearing completion.



Main Building Terrace All Head Room Waterproofing Work In Progress.



Main Building Pour-2 5th Floor Plastering Work Completed.



**Main Building Pour-2 5th Floor Corridor Plastering Work
Completed.**



Main Building Pour-2 4th Floor Corridor Plastering Work Completed.



Main Building Pour-2 3rd Floor Corridor Plastering Work Completed.



Main Building Pour-1 Staircase Plastering Work Completed.



Main Building Pour-2 Staircase Plastering Work Completed.



**Main Building Pour-1 Stilt Floor Ceiling and Column Plastering
Work Completed.**



Main Building Pour-1 Lift-001 Painting Work Completed.



Main Building Pour-2 Podium Area Blockwork Work Completed.



**Main Building Pour-1&2 Staircase Electrical Pipe Laying Work
Completed.**



**Main Building Pour-1 Up to 5th Toilet Electrical Pipe Laying Work
Completed.**



Main Building Electrical Shaft Tray Work In Progress.



Main Building Pour-2 1st Floor Plumbing Work Nearing Completion.



Main Building Pour-2 2nd Floor Plumbing Work In Progress.



Main Building Pour-1 Plumbing Shaft Pipe Laying Work Nearing Completion.



Main Building Pour-2 3rd Floor Sunken Waterproofing Work Completed.



**Main Building Pour-2 4th Floor Sunken Waterproofing
Work In Progress.**



Main Building Pour-2 4th Floor Wall Putty 1 Coat Work In Progress.



**Main Building Electrical and Communication Shaft Painting
Work Completed.**



**Main Building Pour-1 Stilt Floor Ceiling and Column Painting
Work In Progress.**



Main Building Pour-1 1st floor Tiles Work Completed.



Main Building Pour-1 2nd floor Tiles Work Completed.




Main Building Pour-1 3rd floor Tiles Work In Progress.



**Main Building External 1st Series West Side Work Plastering
Completed.**



**Main Building East Side External 4th Series Plastering
Work Completed.**



**Main Building South Side External South side Plastering
Work Completed.**



**Main Building North Side External 1st,2nd& 3rd Series Plastering
Work In Progress.**




Main Building Pour-1 Window Fixing Work Completed.



**Main Building Pour-1 West Side External Texture Painting
Work Completed.**



**Main Building Pour-1 South Side External Texture Painting
Work In Progress.**



Compound Wall Entrance Blockwork Work Completed.

Thank
you!