

# DRA MARINA 100

## MONTHLY CONSTRUCTION PHOTOS JUNE 2026



## **Content**

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
  - ✓ Shell & Core
  - ✓ Block Work
  - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
  - ✓ Toilet Waterproofing
  - ✓ Tile Laying
  - ✓ Painting
  - ✓ MEP Work
  - ✓ Upvc Windows
  - ✓ Joinery
- ❖ External Development

# MASTER PLAN



**DRA MARINA 100**

**Status of Structure & Finishing Work - Summary Report for Month of June'26**

<b>PEARL - Residential Building</b>						
Structure / Floor	Foundation / Footing	Roof Slab	Block Work	Plastering	Internal Finishes	Remarks / Status
UG Sump						
Lower Stilt Floor	📁 Work in Progress					
Upper Stilt Floor	📁 Work in Progress					
1st Floor						
2nd Floor						
3rd Floor						
4th Floor						
5th Floor						
6th Floor						
7th Floor						
8th Floor						
9th Floor						
10th Floor						
11th Floor						
12th Floor						
13th Floor						
Above Terrace -Parapet/OHT/LMR/SHR						
Amenities						
<b>Overall Progress</b>	-	% Completed	-	-	-	

**CORAL - Residential Building**

Structure / Floor	Foundation / Footing	Roof Slab	Block Work	Plastering	Internal Finishes	Remarks / Status
UG Sump						
Lower Stilt Floor	☒ Work in Progress					
Upper Stilt Floor	☒ Work in Progress					
1st Floor						
2nd Floor						
3rd Floor						
4th Floor						
5th Floor						
6th Floor						
7th Floor						
8th Floor						
9th Floor						
10th Floor						
11th Floor						
12th Floor						
13th Floor						
Above Terrace -Parapet/OHT/LMR/SHR						
Amenities						
<b>Overall Progress</b>	-	% Completed	-	-	-	

## Top view



## North side elevation



## South side elevation



## East side elevation



## West side elevation



**Upper Ground Floor Column Retrofitting Reinforcement completed**



## **Upper Ground Floor Retrofitting Shuttering & Concrete Work Completed.**



# First Floor Slab Beam side Shuttering Work In Progress



## First Floor Beam Bottom Laying work In Progress.



*Thank  
you!*