

DRA MARINA 100

MONTHLY CONSTRUCTION UPDATE – JULY 2026



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

MASTER PLAN



Top view



South side elevation



East side elevation



Ground Floor Column Reinforcement & Column Shuttering Concreting work completed



Ground Floor Slab Beam Shuttering Work In Progress



Ground Floor Beam Reinforcement Laying work In Progress



Ground Floor Stair & Lift Wall Chipping work In Progress.



*Thank
you!*