



TRULIV NAVALUR CONSTRUCTION UPDATES - DECEMBER 2023



North Side Elevation



West Side Elevation



South Side Elevation



Eastside Elevation



Internal Flat Painting Work Completed - Upto 11th Floor



Kitchen Granite And Wall Dado Work Completed



Window Grill Fixing Work Completed



CP Fitting Fixing Work Completed



Lift Wall Cladding Work In Progress



Terrace OTS Covering Work In Progress



Silt Floor Grano Flooring Work In Progress



Corridor Handrail Fixing Work Completed



Furniture Fixing Work Completed -Upto 7th floor



Furniture Fixing Work Completed -Upto 7th floor



Interior Work Completed



Basement Fire Fighting and HNS Commissioning Work Completed

INFRASTRUCTURE DEVELOPMENT PROGRESS PHOTOS



External Driveway Work In Progress

OSR PROGRESS PHOTOS



OSR Soil Filling Work In Progress



*Thank
you!*