



TRULIV NAVALUR CONSTRUCTION UPDATES - FEBRUARY 2024



North Side Elevation




South Side Elevation



East Side Elevation



West Side Elevation





Internal Flat Furniture Work



Home Appliances Work



CP and Sanitary Fittings Work



Corridor Painting Work Completed



Lobby Work Completed

INFRASTRUCTURE DEVELOPMENT PROGRESS PHOTOS



Basement Work Completed



External Storm Water Drain Work In Progress



External Paver Laying Work In Progress



External Driveway Light Fixing Work Completed



DG Fixing Work Completed



Transformer Erection Work In Progress



*Thank
you!*